

**2003 Honda CR-V 2.0 SE Sport 5 Door Manual**

Ref: U486


**Specification**

- Make: Honda
- Model: CR-V
- Version: 2.0 SE Sport 5 Door Manual
- Year: 2003
- Registration: SM53 BUU
- VIN: SHSRD87603u125573
- Colour: Green Metallic
- Fuel type: Petrol
- Engine Size: 1998
- Gearbox: Manual
- Vehicle Type: 4 x 4

**Price      £5695**

**Vehicle Features**

- |                     |                          |
|---------------------|--------------------------|
| • Air Conditioning  | • Electric Windows       |
| • Power Steering    | • Air Bags               |
| • ABS               | • CD Radio               |
| • Anti-Theft Device | • Alloy Wheels           |
| • Intelligent 4 x 4 | • Remote Central Locking |
| • Front Fog Lights  |                          |

**Description**

Honda CRV 2.0 SE Sport 5 Door Manual. Green Metallic Paint. First registered on the 29/09/2003 with 1 Lady Owner from new. A full Honda main dealer service history with services carried out at 12377, 22143, 30389, 44029 and 54202 miles. The specification of this practical and reliable Honda CRV includes, Air Conditioning, Sunroof, Alloy Wheels, Intelligent 4 x 4, Electric Windows, Fog Lights and Remote Central Locking. Excellent condition both inside and out. 12 Months MOT, 12 Months Warranty and Service included. Both part exchange and finance available. For further assistance or to arrange a test drive please ring either 0845 3620735 or 0161 7902179.

**John Stuart Motor Company Ltd - Manchester**

Manchester Road  
 Walden  
 M28 3LN  
 United Kingdom

Tel: (+44) 0161 790 2179

**John Stuart Motor Company Ltd - Warrington**

Farrell Street  
 Warrington  
 WA1 2DS  
 United Kingdom

Tel: (+44) 0845 362 0735

Whilst every effort has been taken to ensure accuracy of the above information, some inaccuracies may occur. It is important that you do not rely on this information but check with your dealer about any items which may affect your decision to buy this vehicle. John Stuart Motor Company and their agents accept no liability for loss or damage resulting from errors, omissions or misleading information. These figures relate to a typical example of this model when new. They will vary according to the age, condition, fitted equipment and mileage of the vehicle.